




REPEATED CLEANING OF GEL
FROM TRANSDUCER
MAY RESULT IN
TRANSDUCER DAMAGE



This photograph was supplied by an anesthesiologist. The transducer on his ultrasound unit needed to be replaced as a result of the required cleaning of the gel off of the transducer per standard protocol. It is possible that the wrong cleaning solutions were utilized.

However, this damage might have been prevented with the use of Safersonic Probe Covers as only Safersonic Probe Covers do not require gel under the transducer cover.